

**Huslia: Airport Improvements****FY2008 Request: \$7,525,000**  
**Reference No: 43244****AP/AL:** Allocation  
**Category:** Transportation  
**Location:** Huslia**Project Type:** Construction**House District:** Interior Villages**Contact:** John Torgerson**Contact Phone:** (907)269-0724**Estimated Project Dates:** 07/01/2007 - 06/30/2012**Appropriation:** Airport Improvement Program**Brief Summary and Statement of Need:**

Rehabilitate the safety areas and resurface the runway, taxiway and apron. Apply dust palliative and improve access road. This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.

<b>Funding:</b>	<b>FY2008</b>	<b>FY2009</b>	<b>FY2010</b>	<b>FY2011</b>	<b>FY2012</b>	<b>FY2013</b>	<b>Total</b>
Fed Rcpts	\$7,525,000						\$7,525,000
Total:	\$7,525,000	\$0	\$0	\$0	\$0	\$0	\$7,525,000

<input checked="" type="checkbox"/> State Match Required	<input checked="" type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
5% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

**Operating & Maintenance Costs:**

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	0
Totals:	0	0

**Additional Information / Prior Funding History:**

None.

**Project Description/Justification:**

The runway, taxiway, and apron are in very poor condition and need to be rehabilitated. The existing embankment consists of fine sand. The gravel cap material is not sufficient to prevent erosion and is extremely dusty during dry periods, creating excessive dust plumes during operations. During wet weather the operational surfaces are muddy and severely rutted. Erosion is prevalent all along the safety areas and sideslopes with deep "gully washers" and slump failures. These failures are in danger of impacting the operational surfaces. Several Notices to Airmen have been issued alerting aircraft to poor muddy and rutted conditions. This spring the taxiway was closed due to muddy conditions.